

January 21, 1997

Eric,

I reviewed the latest information submitted for this site, and have identified some information that is needed in order to complete the review.

There are no logs for the geoprobe borings, or any information as to the depths that water samples were obtained.

The new monitor wells have been surveyed, but the ground level and TOC measurements have not been reported in the submittals.

They have submitted a potentiometric surface contour map for measurements taken in December of 1996, but have not included a table of the actual water level measurements. Note that on the contour map they incorrectly labeled MW-8S as MW-4S, so that they have two wells labeled MW-4S.

When we visited the site on October 29, 1996, we told GM about a sewer line that we found on the south side of the property, and asked them to find out more about it. In the December 16, 1996 report they state that they reviewed sanitary sewer maps for the area and confirmed that a sanitary sewer runs along the southern boundary of the site, but state that no laterals from the sewer extend into the site property. I seem to remember that part of this sewer line was actually on the site property. Perhaps we should ask for a copy of the sewer map for that vicinity.

A handwritten signature in cursive script, appearing to read "Cheryl". The signature is written in black ink and is located in the lower right quadrant of the page.