ENVIRONMENT
& HEALTH

Ms. Kim Sakowski
Michigan Department of Environmental, Great Lakes, and Energy
Remediation and Redevelopment Division
Constitution Hall
525 West Allegan Street
Lansing, MI 48909

2022 Annual Inspection Report

Linden Road Landfill
FILE: 1088190/1940102167

January 10, 2023

Ramboll
2090 Commonwealth Blvd.
Ann Arbor, MI 48105
USA

T 734-761-4000
F 734-761-2050
https://ramboll.com

Dear **Ms. Sakowski:**
On behalf of Revitalizing Auto Communities Environmental Response Trust (RACER Trust), Ramboll Americas Engineering Solutions, Inc. (Ramboll) is providing the Michigan Department of Environment, Great Lakes, and Energy with this letter to comply with the Operation & Maintenance reporting requirements at the Linden Road Landfill site in Flint Township, Genesee County, Michigan.

Landfill Cap Inspection
This letter serves to fulfill the Operation & Maintenance (O&M) reporting requirements contained in the O&M Plan dated February 2008 and to satisfy the terms and conditions as described in Section IV, subsection 4.1 of the Agreement for a Limited Recreational Remedy document, Landuse-ERD-98-011, dated June 16, 1999.

The American Youth Soccer Association (AYSO) continues to lease and use the site for recreational purposes and restricts access to the site via a combination lock at the gate to the site. The AYSO also maintains the soil cover by mowing, seeding, filling, as well as setting animal traps, and repairing animal burrows. An inspection report from the December 29, 2022 inspection is included as **Appendix A** to this letter.

As noted in the report, moles have made tunnels and mounds in several areas. The mole activity appeared to be just below the surface and no signs of damage to the final cover or evidence of waste were observed during the inspection.

Ramboll plans to continue working with the AYSO to control the moles and burrowing animals. Otherwise, the landfill cap is in good condition.

If you have any questions regarding the information in this letter, please contact David Favero of RACER Trust at (217) 741-6235 or dfavero@racertrust.org.

Very truly yours,

RAMBOLL AMERICAS ENGINEERING SOLUTIONS, INC.

Clifford S. Yantz
Managing Hydrogeologist
1943864 - MIDWEST EAST Resources 056
M 313.333.0211
Clifford.yantz@ramboll.com

cc: Mr. David Favero – RACER Trust
Mr. Kevin Schneider – Ramboll

APPENDIX A
December 29, 2022
Inspection Report

RACER Trust - Linden Road
Operation and Maintenance Periodic Inspection Report
Flint, MI

INSPECTOR	Kevin Schneider
COMPANY	Ramboll
PROJECT	RACER Trust Linden Road
LOCATION	Flint, MI
DATE/TIME	12/29/2022 13:30
PROJECT NUMBER	1088190/1940102167

WEATHER	CLEAR	P. CLOUDY	CLOUDY	FOG
TEMPERATURE	HIGH	48 F°	--	--
WIND	CALM	MEDIUM	HIGH	--
PRECIPITATION (CIRCLE)	RAIN	LIGHT	MODERATE	HEAVY
	SNOW	LIGHT	MODERATE	HEAVY

TYPE OF INSPECTION: ROUTINE X SPECIAL _____

PERSONS/EQUIPMENT PRESENT: Kevin Schneider,vehicle

GENERAL DESCRIPTION OF SITE CONDITIONS: Grass has been mowed. Overall vegetation cover is in good condition. Vegetation more spare where mole activity observed, no repair need at this time. Perimeter fence is generally in good condition. Along the western perimeter fence there is a limb down, a section of the top rail has been bent due to a tree limb, and an opening in the western perimeter fence was observed.

SPECIFIC INSPECTION ITEMS	POTENTIAL PROBLEM AREAS	STATUS*	NOTES
Perimanent Marker	Covered, Destroyed	1	No issues. Good condition.
Perimeter Security Fencing	Missing barbed wire, torn fabric	2	Opening in fence. Part of top rail bent where limb fell on it.
Entrance Gate and Locking Mechanism	Lock broken/missing, mechanism inoperative	1	No issues. Good condition.
Final Cover Vegetation	Bare spots, stressed vegetation, deep rooted vegetation	1	Sparse vegetation where mole activity observed. see above.
Final Cover Slope (explain below)	Gullies, cracking, subsidence, ponding	1	No issues. Good condition.
Evidence of Burrowing Animals	Damage to final cover, evidence of waste	1	mole activity (see figure)
Stormwater Drainage Channels	Gullies, erosion, debris, culvert blocked	1	No issues. Good condition.
Access Road	Ponding, rutting, erosion	1	No issues. Good condition.

*(1) Acceptable -No Maintenance Required. (2) Not Acceptable-Identify Required Maintenance.

Summary of Deficiencies and/or Corrective Actions: Mole trails should be treated with posion mole peanuts or the grass should be treated with grub treatment to remove the mole food source. The limb on the fence will be removed, the top rail put back into position, and the opening in the fence will be repaired next time on site.

Signature of Inspector: _____

Date: 12/29/2022

I:\Racer-Trust.15388\72204.Linden-2019-Bud\Docs\Reports\Figure 1 Site Layout.mxd

PROJECT: 169000XXXX | DATED: 10/16/2020 | DESIGNER: SCHNEIKB

MOLE ACTIVITY

SPARSE VEGETATION

0 50 100 Feet

SITE LAYOUT

FIGURE 01

RACER TRUST
LINDEN ROAD LANDFILL
FLINT, MICHIGAN

RAMBOLL US CORPORATION
A RAMBOLL COMPANY

RAMBOLL