



**Department
of Commerce**

Division of State Fire Marshal
John R. Kasich, Governor
Andre T. Porter, Director

January 07, 2015

PAMELA BARNETT
RACER TRUST
500 WOODWARD AVENUE
SUITE 1510
DETROIT, MICHIGAN 48226

SITE: GMC HARRISON DIVISION MORaine
(SOUTH TANK FARM)
3600 DRYDEN RD
MORaine OH
MONTGOMERY COUNTY
RELEASE #57000002-N00004

RE: ADDITIONAL INFORMATION REQUESTED

Dear Ms. Barnett:

The Bureau of Underground Storage Tank Regulations (BUSTR) has reviewed your report titled "Tier 1 Investigation" dated October 22, 2014. Based on our review, BUSTR requests the following:

1. Confirmatory sampling was not appropriately conducted at the former location of tank #2 (soil boring SSB-1). Please conduct confirmatory soil sampling pursuant to BUSTR's July 1, 2012 Technical Guidance Manual or install additional borings which delineate this area to delineation levels in all directions.
2. Analytical results from soil boring SSB-3 are consistent with that of sampling conducted during closure activities. Therefore, BUSTR requires delineation of constituents of concern to delineation levels in all directions from this location.
3. Please report the findings of the revised Tier 1 Investigation on the prescribed form.

Please be advised that the transfer of the property will not extinguish your liability to perform the required corrective actions. Publications that may help you to understand the requirements for compliance with BUSTR's rules and regulations may be found on the Internet at <http://www.com.ohio.gov/fire/bustMain.aspx> or by calling our office.

Please submit this information to BUSTR on or before April 08, 2015.

Thank you for your cooperation. If you have any questions, please contact me at (614) 728-1898.

Sincerely,

Bryan Duzak
Environmental Specialist

xc: Site File