

DEPARTMENT OF NATURAL RESOURCES

ENVIRONMENTAL RESPONSE DIVISION

ACTIVITY REPORT

ACTIVITY

- RI/FS
- Complaint Investigation
- Clean-up Activities
- Contractor Oversight
- _____
- Photos Taken
- Samples Taken

PROGRAM

- CERCLA _____
- Act 307 _____
- Act 245 _____
- LUST _____
- Other _____

Facility/Site Name LINDEN ROAD LANDFILL	County Genesee	Date 12-12-96	Time on Activity
Address Linden Road	City/Township Flint	Facility/Site Number	
Participants/Contacts BABU - Weston - 849-918-4018			
Staff VANK. FOR			

REMARKS:

Spoke w/ BABU of WESTON. He indicated they would be sampling MWs 8 and 9 and may not be able to get a full set of samples due to a limited amount of water in wells. Samples will be collected for VOCs, metals, semi-volts, and if enough sample PCBs.

Monitoring wells installed in the interior of the landfill showed BARIUM and arsenic contamination.

GM will be submitting an addendum to RAP addressing MDEQs concerns/comments. The results from MW-8 and 9 will be forwarded as soon as results are available.

Signature Date 12/17/96