

**From:** Sue Kaelber-Matlock  
**To:** DEQ-SC.DEQ-Shiawassee.INNESJ  
**Date:** Tue, Nov 18, 1997 3:08 pm  
**Subject:** Linden Rd Landfill

Hi, I was talking to Joe Medved, my GM corporate environmental contact today. He said Bob Metcalfe had asked him about the wood blocks at Linden Rd. Bob indicated the blocks were not heavily contaminated w/ PCBs, (the draft RAP that I saw didn't indicate concentrations), but there was the concern that they would pop out of the ground and cause a physical hazard. Joe agreed and suggested that GM use a geotextile fabric on top of the blocks and any other debris to keep it in place under the cap. If the blocks are not an eco or human toxicology hazard, this sounds like it might be a reasonable alternative to removing them from the site. Joe Medved also indicated that he had been asked to fly the site for aerial photos this week and that he planned to do that. Sue Kaelber-Matlock  
Senior Geologist  
Saginaw Bay District Office  
Environmental Response Division  
517/686-8025 ext 8303  
ID matlocks  
matlocks@state.mi.us

**CC:** DEQ-SC.DEQ-ERD.SCHULTZD, BROUILLB