

PERMITTEE NAME/ADDRESS
(Include Facility Name/Location if different)

NAME Motors Liquidation Company
ADDRESS: 1451 Lebanon School Road
West Mifflin, PA 15122

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)

(2-16) (17-19)

PA0030392
PERMIT NUMBER

001
DISCHARGE NUMBER

FACILITY: Motor Liquidation Company - Pittsburgh Plant
LOCATION: West Mifflin Borough, Allegheny County

MONITORING PERIOD

FROM	YEAR	MO	DAY	TO	YEAR	MO	DAY
	2009	07	01		2009	07	31

NOTE: Read Instructions before completing this form.

PARAMETER (32-37)	SAMPLE MEASUREMENT PERMIT REQUIREMENT	QUANTITY OR LOADING (46-53) AVERAGE	QUANTITY OR CONCENTRATION (4 Card Only) (38-45)		QUALITY OR CONCENTRATION (46-53)		UNITS	NO. EX (62-63)	FREQUENCY OF ANALYSIS (64-68)	SAMPLE TYPE (69-70)
			MAXIMUM (54-61)	MINIMUM (38-45)	AVERAGE (46-53)	MAXIMUM (54-61)				
Flow	SAMPLE MEASUREMENT PERMIT REQUIREMENT	0.0148	0.66	*	*	*	*	0	2 / month	Measured
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	*	*	*		2 / month	Measured
Oil and Grease	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	<1.0	<1.0	MG/L	0	2 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	15	30			2 / month	Grab
Nitrate Nitrite Nitrogen	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	0.85	0.85	MG/L	0	1 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report			1 / month	Grab
Ammonia Nitrogen	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	0.04	0.04	MG/L	0	1 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report			1 / month	Grab
pH	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	7.4	7.99	S.U.	0	2 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	6.0	9.0		*	2 / month	Grab
Fluoride	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	<0.5	<0.5	MG/L	0	1 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report		*	1 / month	Grab
NAME/TITLE PRINCIPAL EXECUTIVE OFFICER	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	*	*		*	*	*
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report		*	*	*
Wendy White Principal Environmental Engineer, ARCADIS Inc.	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	7.4	7.99	S.U.	0	2 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	6.0	9.0		*	2 / month	Grab
TYPED OR PRINTED	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	<0.5	<0.5	MG/L	0	1 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report		*	1 / month	Grab
COMMENT AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	*	*		*	*	*
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report		*	*	*
On behalf of Motors Liquidation Company	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	7.4	7.99	S.U.	0	2 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	6.0	9.0		*	2 / month	Grab
SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	<0.5	<0.5	MG/L	0	1 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report		*	1 / month	Grab
734 276 0769	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	*	*		*	*	*
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report		*	*	*
DATE	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	7.4	7.99	S.U.	0	2 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	6.0	9.0		*	2 / month	Grab
AREA CODE	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	<0.5	<0.5	MG/L	0	1 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report		*	1 / month	Grab
NUMBER	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	*	*		*	*	*
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report		*	*	*
YEAR	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	7.4	7.99	S.U.	0	2 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	6.0	9.0		*	2 / month	Grab
MO	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	<0.5	<0.5	MG/L	0	1 / month	Grab
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report		*	1 / month	Grab
DAY	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	*	*	*	*		*	*	*
	SAMPLE MEASUREMENT PERMIT REQUIREMENT	*	Monitor & Report	*	Monitor & Report	Monitor & Report		*	*	*

and or maximum imprisonment of between 6 months and 5 years)

Computer Reproduction EPA Form 3320-1