

December 4, 2019

Mr. Paul Bucholtz

Michigan Department of Environment, Great Lakes, and Energy
Remediation and Redevelopment Division
Constitution Hall
525 West Allegan Street
Lansing, MI 48909

RE: 2019 Annual Landfill Cap Inspection
Linden Road Landfill, Flint Township, Genesee County, Michigan
Site ID No. 25000016
FILE: 15388/72204 Docs

Dear **Mr. Bucholtz**:

On behalf of Revitalizing Auto Communities Environmental Response Trust (RACER Trust), O'Brien & Gere, Part of Ramboll is providing the Michigan Department of Environment, Great Lakes, and Energy with this letter to comply with the Operation & Maintenance reporting requirements at the Linden Road Landfill site in Flint Township, Genesee County, Michigan.

LANDFILL CAP INSPECTION

This letter serves to fulfill the Operation & Maintenance (O&M) reporting requirements contained in the O&M Plan dated February 2008 and to satisfy the terms and conditions as described in Section IV, subsection 4.1 of the Agreement for a Limited Recreational Remedy document, Landuse-ERD-98-011, dated June 16, 1999.

The American Youth Soccer Association (AYSO) continues to lease and use the site for recreational purposes and restricts access to the site via a combination lock at the gate to the site. The AYSO also maintains the soil cover by mowing, seeding, filling, as well as setting animal traps, and repairing animal burrows. An inspection report from November 27, 2019 is included as Appendix A to this letter.

As noted in the report, moles have made tunnels and mounds in several areas. The mole activity appeared to be just below the surface and no signs of damage to the final cover or evidence of waste were observed during the inspection. O'Brien & Gere, Part of Ramboll has worked with the AYSO throughout the year to remove the moles by placing solar powered sonic spikes to drive the moles away. O'Brien & Gere, Part of Ramboll plans to continue working with the AYSO to control the moles and burrowing animals. Otherwise, the landfill cap is in good condition.

If you have any questions regarding the information in this letter, please contact David Favero of RACER Trust at (217) 741-6235 or dfavero@racertrust.org.

Very truly yours,
O'BRIEN & GERE ENGINEERS, INC.



Clifford S. Yantz
Senior Hydrogeologist

Enclosures

cc: David Favero, RACER Trust



APPENDIX A
November 27, 2019
Inspection Report

Figure 3-1

**Operation and Maintenance Periodic Inspection Report
Linden Road Site
Flint Township, Michigan**

Inspector Kevin Schneider
 Company O'Brien & Gere
 Project Linden Rd
 Location Flint, MI
 Date/Time 11/27/19
 Project No. 72204

Weather	Clear	P. Cloudy	Cloudy	Fog
Temperature	High	48 F°	---	---
Wind	Calm	Medium	High	---
Precipitation (circle)	<u>Rain</u>	<u>Light</u>	Moderate	Heavy
	Snow	Light	Moderate	Heavy

Type of Inspection Routine Special

Persons/Equipment Present: Kevin Schneider, vehicle

General Description of Site Conditions: site and cover in good condition. Grass has been recently mowed


Specific Inspection Items	Potential Problem Areas	Status*	Notes
Perimeter Security Fencing	Missing barbed wire, torn fabric.	1	
Entrance Gate and Locking Mechanism	Lock broken/missing, mechanism inoperative.	1	
Monitoring Wells and Wellhead Covers	Signs of tampering, casing damaged, lock missing.	N/A	
Final Cover Vegetation	Bare spots, stressed vegetation, deep rooted vegetation.	1	
Final Cover Slope (explain below)	Gullies, cracking, subsidence, ponding.	1	
Evidence of Burrowing Animals	Damage to final cover, evidence of waste.	2	Mole activity
Stormwater Drainage Channels	Gullies, erosion, debris, culvert blocked.	1	
Access Road	Ponding, rutting, erosion.	1	

* (1) Acceptable—No Maintenance Required. (2) Not Acceptable—Identify Required Maintenance.

Summary of Deficiencies and/or Corrective Actions: was raining morning of inspection. water ponded in areas but does not appear to be issue with drainage, will continue to work with soccer association on ways to remove moles. No damage to cover was observed during inspection or signs of waste

Signature of Inspector [Signature]
 Date 11/27/19

11/27/19



0 160'
SCALE

FIGURE 1

LEGEND

- x — PERIMETER FENCING
- • — POST AND CABLE FENCING
- ==== WALKING PATH
- ⊗ PEDESTRIAN GATE
- ⊠ VEHICLE GATE

MONITORING WELL LOCATIONS
RACER Trust
LINDEN ROAD SOCCER FIELDS
Flint Township, Michigan

X = mole activity
Rain during morning of inspection