

December 28, 2017

Mr. Paul Bucholtz

Michigan Department of Environmental Quality
Remediation and Redevelopment Division
Constitution Hall
525 West Allegan Street
Lansing, MI 48909

RE: Annual Landfill Cap Inspection
Linden Road Landfill, Flint Township, Genesee County, Michigan
Site ID No. 25000016
FILE: 15388/64739 Docs

Dear **Mr. Bucholtz**:

On behalf of Revitalizing Auto Communities Environmental Response Trust (RACER Trust), O'Brien & Gere is providing the Michigan Department of Environmental Quality (MDEQ) with this letter to comply with the Operation & Maintenance reporting requirements at the Linden Road Landfill site in Flint Township, Genesee County, Michigan.

LANDFILL CAP INSPECTION

This letter serves to fulfill the Operation & Maintenance (O&M) reporting requirements contained in the O&M Plan dated February 2008 and to satisfy the terms and conditions as described in Section IV, subsection 4.1 of the Agreement for a Limited Recreational Remedy document, Landuse-ERD-98-011, dated June 16, 1999.

The American Youth Soccer Association (AYSO) continues to lease and use the site for recreational purposes, and restricts access to the site via a combination lock at the gate to the site. The AYSO also maintains the soil cover by mowing, seeding, filling, as well as setting animal traps, and repairing animal burrows. An inspection report from November 2, 2017 is included as Appendix A to this letter.

As noted in the report, burrowing animals appear to be present in the soil cover and moles have made tunnels in several areas. O'Brien & Gere plans to continue working with the AYSO to set traps in order to control the moles and burrowing animals. Otherwise, the landfill cap is in good condition.

If you have any questions regarding the information in this letter, please contact David Favero of RACER Trust at (217) 741-6235 or dfavero@racertrust.org.

Very truly yours,
O'BRIEN & GERE ENGINEERS, INC.

Clifford S. Yantz
Scientist-3

Enclosures

cc: David Favero, RACER Trust





APPENDIX A
November 2, 2017
Inspection Report

Figure 3-1

**Operation and Maintenance Periodic Inspection Report
Linden Road Site
Flint Township, Michigan**

Inspector Kevin Schneider
 Company O'Brien & Gere
 Project Linden Rd
 Location Flint, MI
 Date/Time 11/2/17 1500
 Project No. 64739

Weather	Clear	P. Cloudy	Cloudy	Fog
Temperature	High	50 F°	---	---
Wind	Calm	Medium	High	---
Precipitation (circle)	Rain	Light	Moderate	Heavy
	Snow	Light	Moderate	Heavy

Type of Inspection Routine Special

Persons/Equipment Present: Kevin Schneider

General Description of Site Conditions: Grass mowed, overall in good condition

Specific Inspection Items	Potential Problem Areas	Status*	Notes
Perimeter Security Fencing	Missing barbed wire, torn fabric.	1	
Entrance Gate and Locking Mechanism	Lock broken/missing, mechanism inoperative.	1	
Monitoring Wells and Wellhead Covers	Signs of tampering, casing damaged, lock missing.	N/A	
Final Cover Vegetation	Bare spots, stressed vegetation, deep rooted vegetation.	1	
Final Cover Slope (explain below)	Gullies, cracking, subsidence, ponding.	1	
Evidence of Burrowing Animals	Damage to final cover, evidence of waste.	1	1 animal burrow
Stormwater Drainage Channels	Gullies, erosion, debris, culvert blocked.	1	
Access Road	Ponding, rutting, erosion.	1	

* (1) Acceptable—No Maintenance Required. (2) Not Acceptable—Identify Required Maintenance.

Summary of Deficiencies and/or Corrective Actions: Mole activity throughout site, slightly less than previous. should get traps.

Signature of Inspector [Signature]
 Date 11/2/17

11/2/17


Grass clipping Piles

Grass clipping Piles

Grass clipping Piles

Grass clipping Piles

Grass clipping Piles



C:\6032acprj\jbe.dwg