

July 12, 2019

Mr. Eric Van Riper

Senior Project Manager
Michigan Department of Environment, Great Lakes, and Energy
Remediation Division
Constitution Hall, South Tower, 4th Floor
525 W. Allegan Street
Lansing, Michigan 48933

RE: Windiate Park/Dixieland Subdivision Landfill, Pengelly Road Site, Genesee County, Michigan
(Site ID No. 25000689)

FILE: 15388/72201 - Soil Cover Inspection Report

Dear **Mr. Van Riper**:

On behalf of the Revitalizing Auto Communities Environmental Response Trust ("RACER Trust"), O'Brien & Gere Engineers, Inc. (OBG), Part of Ramboll, performed a soil cover inspection at Lot 460 of the Pengelly Road Site on May 17, 2019. The inspection was conducted in accordance with the *Monitoring and Operation & Maintenance Plan* for Lot 460. During the inspection the soil cover was observed to be in good condition. No soil cover repairs are necessary at this time. The completed inspection diagram is attached for documentation.

The next semiannual inspection of the soil cover is scheduled for the fall of 2019.

Please contact me at (313) 333-0211 if you have any questions.

Very truly yours,
O'BRIEN & GERE ENGINEERS, INC.



Clifford S. Yantz
Senior Hydrogeologist

Enclosures

cc: Grant Trigger, RACER Trust
David Favero, RACER Trust




INSPECTION DIAGRAM

CSX PROPERTY ABANDONED RAILROAD

PENGELLY ROAD SITE
LOT 460
FLINT, MICHIGAN

TREES

*Grass will need to
be moved*



INSPECTED BY: Kevin Schneider
(PRINT NAME)

[Signature]
(SIGNATURE)

INSPECTION DATE: 5/17/19

LOT 460
SOIL COVER CONDITION: Good Condition