



September 14, 2009

Mr. Richard Conforti, P.E.
Environmental Engineer
Waste and Hazardous Materials Division
Department of Environmental Quality
PO Box 30241
Lansing, MI 48909-7741

*Subject: Monthly Status Report – August 2009
Coldwater Road Landfill
1245 East Coldwater Road, Flint, MI
MID 005 356 860 / Consent Order No. 64-05-92*

Dear Mr. Conforti:

In accordance with requirements of the above referenced Consent Order, we are providing you with this Monthly Status Report for the month of August 2009.

1. Work Completed This Reporting Period

- Dewatering of the leak detection vaults occurred on August 13, 2009.
- Samples were collected from the accumulation tank and analyzed to verify compliance with the Sewer Use Permit issued by the City of Flint and the Beecher Metropolitan District.
- Landfill cap inspection occurred on August 26, 2009.

2. Summaries of Findings

- During landfill cap inspections, approximately 80 of trees and shrubs were removed and traps were set over active animal burrows.

3. Summaries of Changes

- None.

4. Summaries of all Contact with Local Community

- None.

5. Summaries of all Problems

- None.

6. Actions Being Taken to Rectify Problems

- None.

7. Changes in Personnel

- Ken Richards replaced Scott Haeger as the REALM/Motors Liquidation Company project manager.


8. Projected Work

- Dewatering of the leak detection vaults is scheduled for September 11, 2009.
- Sampling and discharge of accumulated liquids will be conducted as needed.

9. Reports/Data

- Leak detection Vaults A, B, C, D, E and F were pumped on August 13, 2009. During August 2009, no water was removed from Vaults A, and D. However, 92 gallons were removed from Vault B, 89 gallons were removed from Vault C, 268 gallons were removed from Vault E, and 45 gallons were removed from Vault F. Total volume of water removed from the vaults during the month of August was 574 gallons (including rinse water). According to the master flow meter, a total of 1,482 gallons were discharged to the accumulation tank; therefore, 908 gallons were pumped from the sumps during the month of August 2009.

The following graph presents the vault dewatering data in graphical format for the past year:



Please call me at 248-477-5701 if you have any questions.

Very truly yours,

O'BRIEN & GERE ENGINEERS, INC.

Clifford Yantz
Technical Associate

cc: Mr. Ken Richards – Motors Liquidation Company
Ms. Marianne Secrest – O'Brien & Gere