



JOHN ENGLER, Governor

DEPARTMENT OF ENVIRONMENTAL QUALITY

"Better Service for a Better Environment"

HOLLISTER BUILDING, PO BOX 30473, LANSING MI 48909-7973

INTERNET: www.deq.state.mi.us

RUSSELL J. HARDING, Director

REPLY TO:

SHIAWASSEE DISTRICT OFFICE
10650 BENNETT DR
MORRICE MI 48857-9792

April 20, 2000

Mr., Robert Metcalf
General Motors Corporation
902 E. Hamilton Avenue
Mail Code 485-185-020
Flint Michigan 48550-8504

Dear Mr. Metcalf:

SUBJECT: Water Level Measurement of MW-01S and MW-06S at the Linden Road
Landfill, Genesee County

The Michigan Department of Environmental Quality (MDEQ) took water level measurements of the above referenced monitoring wells on April 20, 2000. In order to record the water levels using top of casing as the reference point, the MDEQ had to remove the "J" plugs. Unfortunately, in order to reinstall the J plugs without having the proper keys, the existing pad locks had to be removed and replaced. Enclosed you will find a set of keys that fit both the lock on MW-01S and on MW-06S, as they are keyed alike.

The MDEQ is grateful to you for allowing us to access these monitoring wells as part of our Remedial Investigation of the adjoining Dye Road Dump. We apologize for any inconvenience our changing these locks may cause.

Feel free to contact me if you have any questions.

Sincerely,

A handwritten signature in black ink, appearing to read "James Innes", written over a horizontal line.

James Innes
Environmental Response Division
Shiawassee District Office
(517) 625-4693

JEl:jh

enclosure

cc: Mr. S. Babusukumar, P.G., Roy F. Weston, Inc.