



June 29, 2010

Mr. Eric Van Riper

Senior Project Manager
MDNRE-Remediation and Redevelopment Division
Lansing District Office
Constitution Hall, South Tower, 4th Floor
525 W. Allegan Street
Lansing, Michigan 48933

RE: Windiate Park/Dixieland Subdivision Landfill, Pengelly Road Site, Genesee County, Michigan
(Site ID No. 25000689)

FILE: 14774\46304\Corres

Dear Eric:

On behalf of Motors Liquidation Company, O'Brien & Gere Engineers, Inc. performed a soil cover inspection at Lot 460 of the Pengelly Road Site on June 9, 2010. The inspection was conducted in accordance with the *Monitoring and Operation & Maintenance Plan* for Lot 460. During the inspection the soil cover was observed to be in good condition and no soil cover repairs are necessary at this time. The completed inspection diagram is attached for documentation.

The next semiannual inspection of the soil cover is scheduled for the fall of 2010. Please contact me at (248) 477-5701 if you have any questions.

Very truly yours,

O'BRIEN & GERE ENGINEERS, INC.

Michael B. Robison, CPG
Project Scientist

Enclosure

cc: David Favero, Motors Liquidation Company
Scott Cormier, O'Brien & Gere

INSPECTION DIAGRAM

PENGELLY ROAD SITE
LOT 460
FLINT, MICHIGAN

CSX PROPERTY
ABANDONED RAILROAD

TREES

APPROXIMATE PARCEL BOUNDARY

FENCE

LOT 461

SOIL
COVER
IN GOOD
SHAPE
(NO ROTS
OR HOLES)

LOT 460

60" STM SEWER

APARTMENT
PARKING LOT

APPROXIMATE LOCATION OF
SCHRAM DRAIN

SIDEWALK

PENGELLY ROAD

INSPECTED BY:

MIKE ROBISON (O'BRIEN + GERE)

INSPECTION DATE:

6/9/10



O'BRIEN & GERE
ENGINEERS, INC.

0 25 50
APPROXIMATE SCALE IN FEET