



Mr. Brian Kuberski

Michigan Department of Environment, Great Lakes, and Energy
Remediation and Redevelopment Division
Constitution Hall
525 W. Allegan Street
Lansing, Michigan 48909

RE: Windiate Park/Dixieland Subdivision Landfill, Pengelly Road Site, Genesee County, Michigan
(Site ID No. 25000689)

FILE: 1088190/1940107185 - Soil Cover Inspection Report

Date January 10, 2024

Dear **Mr. Kuberski:**

On behalf of the Revitalizing Auto Communities Environmental Response Trust ("RACER Trust"), Ramboll Americas Engineering Solutions, Inc. (Ramboll), performed a soil cover inspection at Lot 460 of the Pengelly Road Site on November 21, 2024. The inspection was conducted in accordance with the *Monitoring and Operation & Maintenance Plan* for Lot 460. During the inspection the soil cover was observed to be in good condition. No soil cover repairs are necessary at this time. The completed inspection diagram is attached for documentation.

Ramboll
2090 Commonwealth Blvd.
Ann Arbor, MI 48105
USA

T 734-761-4000
F 734-761-2050
<https://ramboll.com>

The next semiannual inspection of the soil cover is scheduled for the spring of 2024.

Please contact me at (313) 333-0211 if you have any questions.

Very truly yours,

RAMBOLL AMERICAS ENGINEERING SOLUTIONS, INC.

Clifford S. Yantz

Project Manager
1943864 - MIDWEST EAST Resources 056

M 313-333-0211
clifford.yantz@ramboll.com

Enclosures
Inspection Diagram


CC: Brendan Mullen – RACER Trust
David Favero – RACER Trust
Kevin Schneider – Ramboll

INSPECTION DIAGRAM

CSX PROPERTY ABANDONED RAILROAD

PENGELLY ROAD SITE
LOT 460
FLINT, MICHIGAN

TREES



INSPECTED BY: Kevin Schneider
(PRINT NAME)

Kevin Schneider
(SIGNATURE)

INSPECTION DATE: November 21, 2024

LOT 460
SOIL COVER CONDITION: Good Condition / Grass has been mowed.



0 25 50
APPROXIMATE SCALE IN FEET