

STATE OF MICHIGAN



JOHN ENGLER, Governor

DEPARTMENT OF ENVIRONMENTAL QUALITY

"Better Service for a Better Environment"

HOLLISTER BUILDING, PO BOX 30473, LANSING MI 48909-7973

INTERNET: www.deq.state.mi.us

RUSSELL J. HARDING, Director

REPLY TO:

SHIAWASSEE DISTRICT OFFICE
10650 BENNETT DR
MORRICE MI 48857-9792

January 5, 2000

Mr, Robert Metcalf
General Motors Corporation
902 E. Hamilton Avenue
Mail Code 485-185-020
Flint Michigan 48550-8504

Dear Mr. Metcalf:

SUBJECT: Results of the Baseline Groundwater Sampling at the Linden Road Landfill,
Genesee County

The Michigan Department of Environmental Quality (MDEQ) has completed its review of the Baseline Groundwater Sampling Report for the above referenced facility, submitted on your behalf by Roy F. Weston, Inc., dated 20 December 1999. The report stated Monitoring Well (MW) 11S contained 0.003 mg/l of vinyl chloride which is above MDEQ Generic Drinking Water Criteria. MW-11S is considered a down gradient monitoring well and therefore any contaminants observed at this location may be migrating off site.

As required in Section 2.4 of the Operation and Maintenance Plan, also identified as Attachment B of the Remedial Action Plan, General Motors is hereby requested to evaluate these results and propose a course of action concerning this matter.

Feel free to contact me if you have any questions.

Sincerely,

A handwritten signature in black ink, appearing to read "James Innes".

James Innes
Environmental Response Division
Shiawassee District Office
(517) 625-4693

JEI:bb

cc: Mr. S. Babusukumar, P.G., Roy F. Weston, Inc.