

**Mr. Eric Van Riper**

Senior Project Manager  
Michigan Department of Environment, Great Lakes, and Energy  
Remediation Division  
Constitution Hall, South Tower, 4<sup>th</sup> Floor  
525 W. Allegan Street  
Lansing, Michigan 48933

RE: Windiate Park/Dixieland Subdivision Landfill, Pengelly Road Site, Genesee County, Michigan  
(Site ID No. 25000689)

FILE: 1088190/1940101410 - Soil Cover Inspection Report

Date January 10, 2022

Dear **Mr. Van Riper:**

On behalf of the Revitalizing Auto Communities Environmental Response Trust ("RACER Trust"), Ramboll Americas Engineering Solutions, Inc. (Ramboll), performed a soil cover inspection at Lot 460 of the Pengelly Road Site on November 18, 2021. The inspection was conducted in accordance with the *Monitoring and Operation & Maintenance Plan* for Lot 460. During the inspection the soil cover was observed to be in good condition. No soil cover repairs are necessary at this time. The completed inspection diagram is attached for documentation.

Ramboll  
2090 Commonwealth Blvd.  
Ann Arbor, MI 48105  
USA

T 734-761-4000  
F 734-761-2050  
<https://ramboll.com>

The next semiannual inspection of the soil cover is scheduled for the spring of 2022.

Please contact me at (313) 333-0211 if you have any questions.

Very truly yours,  
**RAMBOLL AMERICAS ENGINEERING SOLUTIONS, INC.**

A handwritten signature in blue ink that reads "Clifford Scott Yantz".

**Clifford S. Yantz**

Managing Hydrogeologist  
1943864 - MIDWEST EAST Resources 056

M 313-333-0211  
[clifford.yantz@ramboll.com](mailto:clifford.yantz@ramboll.com)

Enclosures


cc: David Favero, RACER Trust  
Kevin Schneider, Ramboll

# INSPECTION DIAGRAM

CSX PROPERTY ABANDONED RAILROAD

PENGELLY ROAD SITE  
LOT 460  
FLINT, MICHIGAN

TREES



INSPECTED BY: Will Laughner  
(PRINT NAME)

Will Laughner  
(SIGNATURE)

INSPECTION DATE: November 18, 2021

LOT 460  
SOIL COVER CONDITION: Good Condition / Grass has been mowed



0 25 50  
APPROXIMATE SCALE IN FEET