

Mr. Eric Van Riper

Senior Project Manager
Michigan Department of Environment, Great Lakes, and Energy
Remediation Division
Constitution Hall, South Tower, 4th Floor
525 W. Allegan Street
Lansing, Michigan 48933

RE: Windiate Park/Dixieland Subdivision Landfill, Pengelly Road Site, Genesee County, Michigan
(Site ID No. 25000689)

FILE: 15388/75088 - Soil Cover Inspection Report

Date June 23, 2021

Dear **Mr. Van Riper:**

On behalf of the Revitalizing Auto Communities Environmental Response Trust ("RACER Trust"), Ramboll Americas Engineering Solutions, Inc. (Ramboll), performed a soil cover inspection at Lot 460 of the Pengelly Road Site on May 20, 2021. The inspection was conducted in accordance with the *Monitoring and Operation & Maintenance Plan* for Lot 460. During the inspection the soil cover was observed to be in good condition. No soil cover repairs are necessary at this time. The completed inspection diagram is attached for documentation.

Ramboll
3600 Green Court
Suite 750
Ann Arbor, MI 48105
USA

The next semiannual inspection of the soil cover is scheduled for the fall of 2021.

T 734-761-4000
F 734-761-2050
<https://ramboll.com>

Please contact me at (313) 333-0211 if you have any questions.

Very truly yours,

RAMBOLL AMERICAS ENGINEERING SOLUTIONS, INC.

A handwritten signature in blue ink that reads "Clifford Scott Yantz".

Clifford S. Yantz

Managing Hydrogeologist
1943864 - MIDWEST EAST Resources 056

M 313-333-0211
clifford.yantz@ramboll.com

Enclosures


cc: David Favero, RACER Trust
Kevin Schneider, Ramboll

INSPECTION DIAGRAM

CSX PROPERTY ABANDONED RAILROAD

PENGELLY ROAD SITE
LOT 460
FLINT, MICHIGAN

TREES



INSPECTED BY: Kevin Schneider
(PRINT NAME)

[Signature]
(SIGNATURE)

INSPECTION DATE: May 20, 2021

LOT 460
SOIL COVER CONDITION: Good Condition / Grass has been mowed



0 25 50
APPROXIMATE SCALE IN FEET