

SITE DESCRIPTION/EXECUTIVE SUMMARY

Site Name and Location

Linden Rd General Motors Landfill  
Linden Road  
Flint, Michigan 48504

County: Genesee  
Michigan Code Number: 25-07N-06E-17AD  
DNR District: Lansing  
EPA ID Number: MID 980608582

SAS Score/Screen No.: 98 547

Linden Road Landfill is owned by General Motors Chevrolet Pressed Metal Division from which it had accepted wastes in the past. The site is presently undergoing regular sampling which has revealed elevated phenols, sulfide, and pH. Also detected was 24 ppb Trans 1,2-Dichloroethane. Contaminants were detected in the sampling of the drift aquifer.

The landfill is located in an area of new residential development and the MDNR Remedial Design unit is concerned about migration of contaminated groundwater off-site. The facility will be undergoing a site inspection for CERCLA purposes in April of 1987.

*- Need to base  
revise on S.I. report*

Date of Previous Summary:  
Previous Author:

Current Date: 3-28-87  
Author: N. Rottschafer

Site Assessment Unit  
Groundwater Quality Division  
Michigan Dept. of Natural Resources