

July 14, 2025

Ms. Nicole Sanabria, & Ms. Christina Hebert

Geologist and Environmental Quality Analyst
Materials Management Division
Department of Environment, Great Lakes, and Energy
PO Box 30241
Lansing, MI 48909-7741

RE: *Semiannual Status Report – January 2025 – June 2025*
Coldwater Road Landfill
1245 East Coldwater Road, Flint, MI
MID 005 356 860
FILE: 1088190/1940113233/Docs

Dear Ms. Sanabria, & Ms. Hebert:

In accordance with requirements of the approved Post-Closure Care Plan, we are providing you with this Semiannual Status Report for the months of January 2025 through June 2025 for activities related to post-closure care for the Coldwater Road Landfill. The status of on-going Site characterization and interim measures related to PFAS will be provided in a separate report.

1. Work Completed This Reporting Period

- » Dewatering of the leak detection vaults occurred on several occasions, as follows: January 16, 2025 (Vaults A through F), February 27, 2025 (Vaults B & E), March 19, 2025 (Vaults B & E), April 14, 2025 (Vaults A through F), May 14, 2025 (Vaults B & E), and June 12, 2025 (Vaults B & E).
- » The annual Groundwater Monitoring, Leak Detection System (LDS), and Landfill Inspection reports were prepared and submitted to EGLE on February 28, 2025.
- » Monitoring well B-19AR was resampled for total organic halides (TOX) on March 7, 2025. A summary and evaluation of the result was sent to EGLE via email on April 15, 2025.
- » The semiannual Groundwater Monitoring, Sump, and LDS sampling was conducted during the week of June 2, 2025. The results will be submitted prior to September 1st in the Semiannual Post-Closure Groundwater Monitoring and Landfill LDS Reports.
- » Sampling of accumulated liquids was conducted on March 5, 2025, and June 10, 2025.
- » The results from the first quarter 2025 Periodic Report on Continued Compliance (PRCC) were shared via email on April 25, 2025. The results of the second quarter 2025 PRCC are due to the City of Flint on or before July 28, 2025, and will be provided to you via email.
- » Discharge of liquids from the accumulation tank for the first quarter occurred on March 26, 2025, and March 27, 2025. The discharge for the second quarter occurred on June 24, 2025 through June 26, 2025. A total of 5,562 gallons were discharged during the first quarter and a total of 8,112 gallons were discharged during the second quarter. Breakthrough and compliance samples were collected from GAC vessels during each quarter and are presented in the quarterly PRCC reports.
- » The first semiannual site inspection occurred on April 28, 2025. No issues of concern were noted during the first semiannual site inspection except for one potentially active animal burrow. A

summary of the findings is presented below. Further details of the inspection will be provided in the Annual Landfill Inspection Report which will be submitted prior to March 1, 2026.

- » Sump F was removed and successfully repaired on January 9, 2025. The necessary maintenance was carried out to ensure optimal functionality and prevent any further issues.

2. Summaries of Findings

- » Observed one potentially active animal burrow on April 28, 2025. A trap was set at the animal burrow. The animal burrow was found to be inactive. The animal burrow was backfilled and closed out on May 19, 2025, and a photo log and figure are included as an appendix to this report.

3. Summaries of Changes

- » None.

4. Summaries of all Contact with Local Community

- » None.

5. Summaries of all Problems

- » None.

6. Actions Being Taken to Rectify Problems

- » None.

7. Changes in Personnel

- » None.

8. Projected Work

- » Dewatering of the leak detection vaults is scheduled for July 16, 2025 (All Vaults), August 13, 2025 (if necessary due to volume), September 17, 2025 (Vault B & E, if necessary), October 15, 2025 (All Vaults), November 12, 2025 (if necessary due to volume), and December 17, 2025 (Vault B & E, if necessary).
- » Sampling and discharge of accumulated liquids will be conducted as needed.
- » The second semiannual site inspection will be conducted in October 2025.
- » The second semiannual Groundwater Monitoring and LDS sampling will be conducted in November 2025.

9. Reports/Data

» The following table presents the vault dewatering and monthly leachate sump data for January through June 2025:


DATE	GALLONS LEAK DET	GALLONS LEAK DET	GALLONS LEAK DET	GALLONS LEAK DET	GALLONS LEAK DET	GALLONS LEAK DET	TOTAL LEAK GALLONS	MONTHLY SUMP VOLUMES GALLONS
2025	A	B	C	D	E	F		
16-Jan-25	239*	576*	34*	3*	712	4*	1,568	871
27-Feb-25	--	225	--	--	369	--	594	876
19-Mar-25	--	262	--	--	704	--	966	687
14-Apr-25	199*	429	74*	5*	1,278	6*	1,991	1,012
14-May-25	--	387	--	--	1,241	--	1,628	749
12-Jun-25	--	490	--	--	967	--	1,457	1,275
TOTAL	438	2,369	108	8	5,271	10	8,204	5,470

* Indicates 2-month totals.

Note:

Total volume of water removed from the vaults from January through June 2025 was 8,204 gallons. According to the master flow meter and discharge records, a total of 5,470 gallons were pumped from the leachate collection sumps from January through June 2025.

The following graph presents the vault dewatering data in graphical format for the past 12 months:



10. Active Post-Closure Care Task 2025 Budget Status

- » Task 1 – Continue Ongoing OMM: 50% complete, 56% of 2025 budget.
- » Task 6 – Agency Coord./Negotiation & Reporting: 50% complete, 50% of 2025 budget.
- » Task 7 – Project Management & Coordination: 50% complete, 53% of 2025 budget.

Please call me at 313-333-0211 if you have any questions.

Very truly yours,

Ramboll Americas Engineering Solutions, Inc.



Clifford S. Yantz

Project Manager

1943864 - MIDWEST EAST Resources 056

M 313.333.0211

Clifford.yantz@ramboll.com

cc: Brendan Mullen – RACER Trust
 David Favero – RACER Trust
 Kevin Schneider – Ramboll
 EGLE MMD

Certification

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision according to a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.


On Behalf of RACER Trust

A handwritten signature in blue ink that reads "Clifford Scott Yantz". The signature is written over a horizontal line.

Clifford S. Yantz
Project Manager – Ramboll Americas Engineering Solutions, Inc.
As agent for RACER Trust

Date: July 14, 2025

cc: file



- ⊗ ANIMAL BURROW LOCATION (NOT ACTIVE)
- ⊙ LEACHATE COLLECTION SUMP
- ACCESS PORT FOR LEAK DECTION VAULT

ANIMAL BURROW LOCATION MAP 2ND QUARTER 2025



FIGURE 01



RACER TRUST
COLDWATER ROAD
FLINT, MICHIGAN

RAMBOLL AMERICAS
ENGINEERING SOLUTIONS, INC.
A RAMBOLL COMPANY



LOCATION: Cell A1		APPROX. LENGTH: 5+ feet	APPROX. DEPTH: 1 foot	APPROX. DIAMETER: 6 inches
DATE FOUND: 4/28/25	DATE CLOSED: 5/19/25			
NOTES: ID: 2025-05-19-066 PRE repair photo. Trap set for twenty-one days. No activity. No signs of liner damage.				
LOCATION: Cell A1		APPROX. LENGTH: 5+ feet	APPROX. DEPTH: 1 foot	APPROX. DIAMETER: 6 inches
DATE FOUND: 4/28/25	DATE CLOSED: 5/19/25			
NOTES: Post repair photo. Filled in burrow.				