

DEPARTMENT OF NATURAL RESOURCES

ENVIRONMENTAL RESPONSE DIVISION

ACTIVITY REPORT

ACTIVITY

- RI/FS
- Complaint Investigation
- Clean-up Activities
- Contractor Oversight
- _____
- Photos Taken
- Samples Taken

PROGRAM

- CERCLA _____
- Act 307 _____
- Act 245 _____
- LUST _____
- Other _____

Date <u>10/29/96</u>		Time on Activity
Facility/Site Name <u>Linden Road Landfill</u>	County <u>GENESSEE</u>	Facility/Site Number
Address <u>Linden Road</u>	City/Township <u>FLINT</u>	Staff <u>VAN Riper / STANFIELD</u>
Participants/Contacts		

REMARKS: SITE VISIT BY ERIC VAN RIPER & CHERYL STANFIELD, MDEC.

WALKED PROPERTY AND OBSERVED DRILLING ACTIVITIES. VERY LITTLE WASTE MATERIAL PRESENT ON SURFACE OF SITE. NUMEROUS RUSTED DRUMS LOCATED IN DYE ROAD DUMP.

Met w/ Bob Mercalf & BABU. DRILLERS COULD NOT GET ACCESS TO PROPOSED WELL AT NE CORNER BECAUSE OF ROUGH GROUND. SUGGESTED TO GM TO GO OFF LINDEN ROAD THROUGH FENCE.

BABU STATED THAT VERY LITTLE WATER ENCOUNTERED IN PROPOSED Boring GP-1. INFORMED HIM WE WOULD LIKE 5 DISTANCE GROUNDWATER SAMPLES (IF HE HAS PROBLEMS, SUGGESTED HE CONTACT MDEC AT THAT TIME.

BOB MERCALF WILL INVESTIGATE SOUTHERLY MOUND HOLE COVER LOCATED ALONG SOUTH PROPERTY LINE. WHERE IS LINE GOING.

Signature [Signature] Date 10/29/96

Distribution:

ADD ADDITIONAL SHEETS AS NECESSARY

R 5532

Original - District File

6/87

Canary - Regional Supervisor

Pink - Other