

Mr. Eric Van Riper

Senior Project Manager
Michigan Department of Environment, Great Lakes, and Energy
Remediation Division
Constitution Hall, South Tower, 4th Floor
525 W. Allegan Street
Lansing, Michigan 48933

RE: Windiate Park/Dixieland Subdivision Landfill, Pengelly Road Site, Genesee County, Michigan
(Site ID No. 25000689)

FILE: 15388/75088 - Soil Cover Inspection Report

Date August 10, 2020

Dear **Mr. Van Riper:**

On behalf of the Revitalizing Auto Communities Environmental Response Trust ("RACER Trust"), O'Brien & Gere Engineers, Inc., a Ramboll Company (Ramboll), performed a soil cover inspection at Lot 460 of the Pengelly Road Site on May 28, 2020. The inspection was conducted in accordance with the *Monitoring and Operation & Maintenance Plan* for Lot 460. During the inspection the soil cover was observed to be in good condition. There was an area with shallow ruts with exposed soil. The shallow ruts and exposed soil is not considered a concern at this time. Ramboll will level the ruts and spread grass seed in the area to promote growth during the next visit to the site. No additional soil cover repairs are necessary at this time. The completed inspection diagram is attached for documentation.

Ramboll
2260 E. Saginaw Street
East Lansing, MI 48823
USA

T 414-837-3607
F 414-837-3608
<https://ramboll.com>

The next semiannual inspection of the soil cover is scheduled for the fall of 2020. Please contact me at (313) 333-0211 if you have any questions.

Yours sincerely



Clifford S. Yantz

Senior Hydrogeologist
1943864 - MIDWEST EAST Resources 056

M 313-333-0211
clifford.yantz@ramboll.com

Enclosures


cc: David Favero, RACER Trust

INSPECTION DIAGRAM

CSX PROPERTY ABANDONED RAILROAD

PENGELLY ROAD SITE
LOT 460
FLINT, MICHIGAN

TREES



INSPECTED BY: Will Laughner
(PRINT NAME)

Will Laughner
(SIGNATURE)

INSPECTION DATE: 5/28/20

LOT 460
SOIL COVER CONDITION: Good Condition