



December 30, 2010

Mr. Eric Van Riper
Senior Project Manager
Michigan Department of Natural Resources and Environment
Remediation Division
Constitution Hall, South Tower, 4th Floor
525 W. Allegan Street
Lansing, Michigan 48933

RE: Windiate Park/Dixieland Subdivision Landfill, Pengelly Road Site, Genesee County, Michigan
(Site ID No. 25000689)

FILE: 14774\46304\Docs\Reports

Dear Eric:

On behalf of Motors Liquidation Company, O'Brien & Gere Engineers, Inc. performed a soil cover inspection at Lot 460 of the Pengelly Road Site on October 28, 2010. The inspection was conducted in accordance with the *Monitoring and Operation & Maintenance Plan* for Lot 460. During the inspection the soil cover was observed to be in good condition and no soil cover repairs are necessary at this time. The completed inspection diagram is attached for documentation.

The next semiannual inspection of the soil cover is scheduled for the spring of 2011. Please contact me at (248) 477-5701 if you have any questions.

Very truly yours,

O'BRIEN & GERE ENGINEERS, INC.

Michael B. Robison, CPG
Project Scientist

Enclosure


cc: David Favero, Motors Liquidation Company
Scott Cormier, O'Brien & Gere

INSPECTION DIAGRAM

CSX PROPERTY ABANDONED RAILROAD

PENGELLY ROAD SITE
LOT 460
FLINT, MICHIGAN

TREES



INSPECTED BY: Mike Robison
(PRINT NAME)

[Signature]
(SIGNATURE)

INSPECTION DATE: 10/28/10

LOT 460
SOIL COVER CONDITION: GOOD. NO RUTS OBSERVED.



0 25 50
APPROXIMATE SCALE IN FEET