

December 21, 2015

Mr. James Innes
Environmental Quality Analyst
Michigan Department of Environmental Quality
Remediation Division
Lansing District Office
PO Box 30242
Lansing, MI 48909

RE: Annual Landfill Cap Inspection
Linden Road Landfill, Flint Township, Genesee County, Michigan
Site ID No. 25000016
FILE: 15388/60777 Docs

Dear **Mr. Innes**:

On behalf of Revitalizing Auto Communities Environmental Response Trust (RACER Trust), O'Brien & Gere is providing the Michigan Department of Environmental Quality (MDEQ) with this letter to comply with the Operation & Maintenance reporting requirements at the Linden Road Landfill site in Flint Township, Genesee County, Michigan.

LANDFILL CAP INSPECTION

This letter serves to fulfill the Operation & Maintenance (O&M) reporting requirements contained in the O&M Plan dated February 2008 and to satisfy the terms and conditions as described in Section IV, subsection 4.1 of the Agreement for a Limited Recreational Remedy document, Landuse-ERD-98-011, dated June 16, 1999.

The American Youth Soccer Association (AYSO) continues to lease and use the site for recreational purposes, and restricts access to the site via a combination lock at the gate to the site. The AYSO also maintains the soil cover by mowing, seeding, filling, as well as setting animal traps and repairing animal burrows. An inspection report from November 10, 2015 is included as Appendix A to this letter.

As noted in the report, burrowing animals appear to be present in the soil cover and moles have made tunnels in several areas. O'Brien & Gere plans to continue working with the AYSO to set traps in order to control the moles and burrowing animals. Otherwise, the landfill cap is in good condition.

If you have any questions regarding the information in this letter, please contact David Favero of RACER Trust at (217) 741-6235 or dfavero@racertrust.org.

Very truly yours,
O'BRIEN & GERE ENGINEERS, INC.

Clifford S. Yantz
Scientist-3

Enclosures

cc: David Favero – RACER Trust

I:\Racer-Trust.15388\60777.Linden-Rd-Lf-20\Docs\Reports\Annual Inspection Report 11-2015.docx





Appendix A
November 10, 2015
Inspection Report

Figure 3-1

**Operation and Maintenance Periodic Inspection Report
Linden Road Site
Flint Township, Michigan**

Inspector Kevin Schneider
 Company O'Brien & Gere
 Project Linden Rd Landfill
 Location Flint, MI
 Date/Time 11/10/15 1300
 Project No. 60777

Weather	Clear	P. Cloudy	<u>Cloudy</u>	Fog
Temperature	High	<u>50</u> F°	---	---
Wind	<u>Calm</u>	Medium	High	---
Precipitation (circle)	Rain	Light	Moderate	Heavy
	<u>NONE</u>	Snow	Light	Moderate

Type of Inspection Routine Special

Persons/Equipment Present: Kevin Schneider / Company TRUCK

General Description of Site Conditions: Good condition: the grass was mowed along the eastern soccer fields but grass was high on the western soccer fields

Specific Inspection Items	Potential Problem Areas	Status*	Notes
Perimeter Security Fencing	Missing barbed wire, torn fabric.	1	
Entrance Gate and Locking Mechanism	Lock broken/missing, mechanism inoperative.	1	
Monitoring Wells and Wellhead Covers	Signs of tampering, casing damaged, lock missing.	N/A	
Final Cover Vegetation	Bare spots, stressed vegetation, deep rooted vegetation.	1	
Final Cover Slope (explain below)	Gullies, cracking, subsidence, ponding.	1	
Evidence of Burrowing Animals	Damage to final cover, evidence of waste.	1	2 burrows observed NO damage to liner
Stormwater Drainage Channels	Gullies, erosion, debris, culvert blocked.	1	
Access Road	Ponding, rutting, erosion.	1	few pot holes in access road


* (1) Acceptable--No Maintenance Required. (2) Not Acceptable--Identify Required Maintenance.

Summary of Deficiencies and/or Corrective Actions: A number of mole trails were observed along the outside of eastern soccer fields. 2 animal burrows were located on the east side of the western soccer fields. along the western perimeter fence the top rail was knocked off by a tree limb.

Signature of Inspector [Signature] Date 11/10/15

off of fence
of Rail

11/10/15



⊗ mole mounds
 ~ mole trails
 ⊗ animal burrows