



Nodular/ENV/Compliance/Misc

Eave T.

STATE OF MICHIGAN
DEPARTMENT OF ENVIRONMENTAL QUALITY
REMEDIATION DIVISION

FACILITY INSPECTION REPORT

Owner Name & Address:

Revitalizing Auto Communities
Environmental Response
2930 Ecorse Rd
Ypsilanti, MI 48198

Location of Tanks:

Saginaw Metal Casting Operations
1629 N Washington Ave
Saginaw, MI 48601-1211
County - Saginaw
Facility ID - 00010581

ATTENTION: Ray Illka

An Existing Facility Inspection was conducted on May 23, 2012, for the above-referenced facility for compliance with Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Michigan Underground Storage Tank Rules (MUSTR), 2008 AACS R 29.2101 et seq.; and the applicable sections of the rules for the Storage and Handling of Flammable and Combustible Liquids, 2003 AACS R 29.5101 et seq. The inspection showed that the facility is approved.

Inspection finds no violations. This facility is approved until next inspection.

If you have additional questions concerning this matter, please contact me.

Michael DeWyse

Michael DeWyse
Hazardous Materials Storage Inspector
Saginaw Bay District Office
401 Ketchum Street, Suite B
Bay City, MI 48708
Phone: (989) 894-6294
Fax: (989) 891-9237
Email: dewysem1@michigan.gov

5/25/12

Date

RECEIVED MAY 29 2012