

November 29, 2018

Mr. Paul Bucholtz

Michigan Department of Environmental Quality Remediation and Redevelopment Division Constitution Hall 525 West Allegan Street Lansing, MI 48909

> RE: Annual Landfill Cap Inspection Linden Road Landfill, Flint Township, Genesee County, Michigan Site ID No. 25000016

FILE: 15388/68489 Docs

Dear Mr. Bucholtz:

On behalf of Revitalizing Auto Communities Environmental Response Trust (RACER Trust), O'Brien & Gere is providing the Michigan Department of Environmental Quality (MDEQ) with this letter to comply with the Operation & Maintenance reporting requirements at the Linden Road Landfill site in Flint Township, Genesee County, Michigan.

LANDFILL CAP INSPECTION

This letter serves to fulfill the Operation & Maintenance (0&M) reporting requirements contained in the 0&M Plan dated February 2008 and to satisfy the terms and conditions as described in Section IV, subsection 4.1 of the Agreement for a Limited Recreational Remedy document, Landuse-ERD-98-011, dated June 16, 1999.

The American Youth Soccer Association (AYSO) continues to lease and use the site for recreational purposes, and restricts access to the site via a combination lock at the gate to the site. The AYSO also maintains the soil cover by mowing, seeding, filling, as well as setting animal traps, and repairing animal burrows. An inspection report from October 30, 2018 is included as Appendix A to this letter.

As noted in the report, one animal burrow appeared to be present in the soil cover and moles have made tunnels in several areas. During the inspection it was not clear whether it was new mole activity or old activity. O'Brien & Gere plans to continue working with the AYSO to set traps in order to control the moles and burrowing animals. Otherwise, the landfill cap is in good condition.

If you have any questions regarding the information in this letter, please contact David Favero of RACER Trust at (217) 741-6235 or dfavero@racertrust.org.

Very truly yours,

O'BRIEN & GERE ENGINEERS, INC.

Clifford S. Yantz Scientist-3

Enclosures

cc: David Favero, RACER Trust



APPENDIX A
October 30, 2018
Inspection Report

Figure 3-1

Operation and Maintenance Periodic Inspection Report Linden Road Site Flint Township, Michigan

7	•	0			
Inspector KEVIN SCHNEIDE				~	
Company O'BURN & Gerl	Weather	Clear	P. Cloudy	Cloudy	Fog
Project Linden &d LF	Temperature	High	44 Fo	000	
Location Flint, MI	Wind	Calm	Medium	High	u = 0
Date/Time 10/30/18 140	Precipitation (circle)	Rain	Light	Moderate	Heavy
Project No. 68489		Snow	Light	Moderate	Heavy
Persons/Equipment Present: General Description of Site Conditions: Overall in good conditions	Special [] Kenn Schnender GRASS Mowed @	all but	jwo Sold	er field:	
Specific Inspection Items Potential Problem Areas			Status*	Notes	
erimeter Security Fencing Missing barbed wire, torn fabric.			l	Tree limb laying	
Entrance Gate and Locking Mechanism Lock broken/missing, mechanism inoperative.			i		
Monitoring Wells and Wellhead Covers Signs of tampering, casing damaged, lock missing.			NA		
Final Cover Vegetation Bare spots, stressed vegetation, deep rooted vegetation.					
Final Cover Slope (explain below) Gullies, cracking, subsidence, ponding.			ì		
vidence of Burrowing Animals Damage to final cover, evidence of waste.			2	are animo	nt located/
Stornwater Drainage Channels	Gullies, erosion, debris, culvert blocked.				
Access Road	Ponding, rutting, erosion.	1			
*(1) Acceptable—No Maintenance Required. Summary of Deficiencies and/or Corrective Active. Una 15 active of from		und an	i i	maimal	lasted burier

X- Mole Activity 1. Mo Cence SOCCER FIELD SOCCER FIELD SOCCER FIELD SOCCER FIELD SOCCER FIELD 6 0 × X O Annal Burrow Cable PARKING AREA Jours x X X XX X SOCCER FIELD SOCCER FIELD RETENTION X X X X X X 160' FIGURE LEGEND SCALE VEHICLE GATE MONITORING WELL LOCATIONS **RACER Trust** PERIMETER FENCING POST AND CABLE FENCING LINDEN ROAD SOCCER FIELDS WALKING PATH Flint Township, Michigan ⊗ PEDESTRIAN GATE

C:\6.05geoprobe.dwg